


CORNER RECORD

Near East City Limits of Portola

Document Number _____

County of Plumas, California

Brief Legal Description Located in Section 30, T. 23 N., R. 14 E., M.D.M.



CORNER TYPE

Government Corner Control

COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey MAY, 1994

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found 3/4" I.P. tagged LS 3297 at S.E. corner of Parcel 2, 1 PM 38, also found Bolt at N.E. corner of said Parcel 2. 3/4" I.P. 244.00' North of S.E. corner of said Parcel 2 appeared to have been destroyed when power pole was set. Reset missing 3/4" I.P. in record position between found corners.

A description of the physical condition of the monument as found and as set or reset: Reset 5/8" rebar with aluminum cap LS 2843 in place of missing 3/4" I.P., N 00°04'10" E, 244.00' from S.E. corner of Parcel 2, 1 M 38.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on August 20, 1994.


Signed John W. Hamby L.S. 2843
John W. Hamby




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 10/3 1994 and
examined and filed 10/12 1994.

Signed R. Tom Fletcher Title _____



County Surveyor's Comment _____



LEGEND

- FOUND point as described
- SET 5/8" rebar with aluminum cap LS 2843
- (R1) RECORD per 1 PM 38