

CORNER RECORD


Document Number _____

Section 11, T. 23 N., R. 11 E., M.D.M.

County of Plumas

, California

Brief Legal Description Parcel shown on 1 RS 80, Plumas County records.



CORNER TYPE

Government Corner Control Meander Property Rancho Other

Date of Survey September 20, 1996

COORDINATES
(Optional)

N. _____

E. _____

Zone _____ Datum _____

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found 3/4" I.P. tagged LS 2587 at fence intersection at Southeast corner of parcel shown on 1 RS 80, found 6"x 6" concrete monument at Northwest corner of said 1 RS 80, (map called for 3/4" I.P.) as shown in attached sketch.

A description of the physical condition of the monument as found and as set or reset: The 2"x 2" hubs shown along the South line were missing. Set 5/8" rebar with Plastic Cap LS 2843.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on September 20, 1996.

Signed *John W. Hamby* L.S. 2843
John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 10/15 1996 and
examined and filed 11/1 1996.

Signed *R. Tom Stanton* Title Co Surveyor



County Surveyor's Comment _____

Found 6"x 6" Concrete Monument
map called for 3/4" I.P.



$$1'' = 100'$$

1" = 100'

State Highway 89

50'

50'

1 RS 80

Set 5/8" rebar with Aluminum Cap stamped LS 2843

Found Brass Cap B.P.R. "1928"

Found 3/4" I.P. tagged LS 2587

Found 3/4" I.P. with Plastic Plug LS 3297

Found 3/4" I.P. tagged LS 2587

N30°21'30"E
49.60'

N49°54'30"W
214.87'

S65°45'30"E
381.21'

N62°05'30"W
131.31'

N47°27'30"W
383.13'

N24°11'02"E 236.66'
(N24°14'30"E 236.70' mea.
rec.)