


CORNER RECORD

Section 15 T.24N.R.9E. MDM

Document Number 185County of Plumas, CaliforniaBrief Legal Description Parcel 3, per 3 PM 55

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey Oct. 17, 2000

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
 Monuments found were 1" Iron Pipe Tagged LS 2702 at locations indicated on 3 PM 55.

A description of the physical condition of the monument as found and as set or reset:

The Northwest monument was missing. Since there was no way to proportion the reset, we set the replacement monument by distance—distance from found monuments.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act in October, 2000.


Signed John W. Hamby L.S. 2843
 John W. Hamby




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 11/15 2000 and
 examined and filed 11/20 2000.

Signed R. Tom Slawter Title Co. Surveyor



County Surveyor's Comment _____



● Found 1" I.P. tagged LS 2702

○ Set 5/8" Rebar with Alum. cap LS 2843

(R1) Record per 3 PM 55