


## CORNER RECORD

Document Number 191Sec 24, T22N R11ECounty of PLUMAS, CaliforniaBrief Legal Description LOT 53 JOHNSVILLE

## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey 12-28-99

Elev. \_\_\_\_\_

Corner- Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 1" Iron Pipe tagged RCE 7567 as indicated on the attached drawing, and as shown on  
 the PLAT OF TOWNSITE OF JOHNSVILLE, filed in the office of the Recorder of Plumas County  
 in book 3 of Maps at page 34.


A description of the physical condition of the monument as found and as set or reset:

The monuments found were in good condition and except as shown were in record locations. The  
 monuments set were set as shown on 3 M 34. The original monuments appeared to have been  
 destroyed by road work.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in  
 conformance with the Land Surveyors' Act on Dec. 28, 1999.

Signed John W. Hamby L.S. 2843  
 John W. Hamby



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1/22 2000 and  
 examined and filed 1/24 2000.

Signed Tom Hunter Title C. Surveyor

County Surveyor's Comment \_\_\_\_\_



## LEGEND

- FOUND 1" iron pipe tagged RCE7567 per 3 M 34, or as noted.
- SET 5/8" Rebar & Aluminum Cap LS 2843



1" = 50'

