


CORNER RECORD

Document Number 194

Section 12, T. 23 N., R. 13 E., M.D.M.

County of Plumas, CaliforniaBrief Legal Description Lot 18, Lake Davis Highlands Subdivision Unit No. Two, 4 M 39A

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey March 30, 2001COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found 3/4" iron pipes as shown on attached sketch from which I set missing corners in record locations.

A description of the physical condition of the monument as found and as set or reset: From found corners shown on attached sketch I set 5/8" rebars with Aluminum Caps stamped LS 2843 in record location as shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 3, 2001.


Signed John W. Hamby L.S. 2843
 John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 18th 2001 and examined and filed May 2nd 2001.

Signed R. Tom Stanton Title County Surveyor



County Surveyor's Comment _____

Set 5/8" rebar &
Aluminum Cap LS 2843

Lakeview Circle

S80°20'11"E
155.67'

Found 3/4" I.P.
tagged 7294

Found 3/4" I.P.
with wood plug

N27°20'02"W
472.80'

1" = 100'



Lot 18
4 M 39A

Set 5/8" rebar &
Aluminum Cap LS 2843

N17°33'26"W
241.14'

N89°36'06"W
160.00'

Found 3/4" I.P.
tagged 7294

Lot 18, Lake Davis Highlands
Subdivision Unit No. Two

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571

01031