


CORNER RECORD

Document Number 196

Section 16, T. 22 N., R. 12 E., M.D.M.

County of Plumas, California

Brief Legal Description Lot 16, Gold Ridge Subdivision Unit No. 2, Book 6 Maps Page 68



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey June 14, 2001

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found Northeast, Southeast and Southwest corners of Lot 16 from which I established reference monuments on the top of Bank of the creek on the Northerly and Westerly line of Lot 16 as shown in sketch.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with Aluminum Cap stamped LS 2843 on Top Bank of creek for reference monument to Northwest corner of Lot 16 which is missing due to being washed out by highwater.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on June 25, 2001.

Signed John W. Hamby L.S. 2843
 John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 18th 2001 and
 examined and filed July 2nd 2001.

Signed R. Tom Hunter Title P.C. Engineer




County Surveyor's Comment _____

NOTE:

Northwest Corner and reference point on North
line of Lot 16 missing due to highwater.



1" = 50'



LEGEND

- FOUND Rebar with Aluminum Cap RCE 13225
- SET Rebar with Aluminum Cap LS 2843
for reference points to Northwest corner of Lot 16
- (R&M) Record and measured per 6 M 68