


CORNER RECORD

Document Number 261

IN THE NE1/4, SEC. 25, T.22N., R12E., M.D.M.

County of PLUMAS, CaliforniaBrief Legal Description LOT 4 OF THE RIVER'S EDGE SUBDIVISION IN 5 M 117-118

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey JANUARY, 2004

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points as shown and described on attached sketch and as shown on 5 M 117-118.

A description of the physical condition of the monument as found and as set or reset:

Found points as described and in good condition. Points set as shown on attached sketch, as witness corners to actual property corner, which falls in river.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on January 19, 2004.

Signed J W Hamby L.S. 2843
John W. Hamby


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-15 2004 and
examined and filed 2/10/04 2004.Signed R Tom Shumate Title Engineer

County Surveyor's Comment _____

NOTE:
Set new witness corners to the rear property
corners due to erosion of bank destroyed the
original RPs.

Found 1/2" Rebar



LEGEND

- FOUND point as described
- SET 5/8" Rebar & Aluminum Cap LS 2843
Stamped W.C.

03336

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571