


CORNER RECORD

Document Number 266City of _____ County of PLUMAS, CaliforniaBrief Legal Description E 1/16 between Sections 29 & 32; T.26 N., R.10 E, MDM

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey May 26, 2004

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Corner evidence was destroyed, nothing found. The 3/4" pipe, tagged RCE7294 was tied by me in 1998 and documented on Record of Survey Book 11, at Pages 55 to 59. I was able to recover my old control and set a replacement monument in the previous position.

A description of the physical condition of the monument as found and as set or reset: The old monument and both bearing trees were destroyed by the construction of a logging skid road. I placed a new monument being a 5/8" rebar with a 1-1/2" Aluminum cap, stamped RCE 29700 in a 28" dia. by 8" high stone mound on western edge of skid road. I also scribed two new bearing trees as outlined on the sketch on other side.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on May 28 2004

Signed Richard R. Simpson XX or R.C.E. Number 29700
Expires 3-31-07



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 1, 2004 10 and examined
 and filed June 21, 2004 10.

Signed R. Tom Hunter Title Plumas Co. Engineer



County Surveyor's Comment _____

LEGEND:

- FOUND 5/8" REBAR W/ 1- 1/2" ALUM. CAP MKD: RCE 29700
- ⊗ FOUND BLM(BRASS) CAPPED MONUMENT.
- SET 5/8" REBAR W/ 1- 1/2" ALUM. CAP MKD: RCE 29700

NOT TO SCALE

