


CORNER RECORD

Document Number 284

Portion Section 1 T.22N.R.13E MDM

County of Plumas, CaliforniaBrief Legal Description Lot 88 Ridgewood Subdivision 5 M 45

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey Sept.22, 2003

Elev. _____


Corner- Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found points indicated on attached sketch in good condition.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar capped LS 2843 at locations indicated.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on September 22, 2003.

Signed John W. Hamby L.S. 2843
John W. Hamby


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 8th 2005 and
examined and filed 5/31/ 2005.Signed R. Tom Stanton Title Plumas Co.
Engineer

County Surveyor's Comment _____

- FOUND 1/2" Rebar p 5 M 45
- SET 5/8" Rebar & Aluminum Cap LS 2843
- Not found or set

(R1) RECORD per 5 M 45



RIDGEWOOD SUBDIVISION

Section 1 T.22N.R.13E. MDM

Plumas County, Ca.

Scale 1" = 50' Sept., 2003

03238

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571