


CORNER RECORD

Document Number 320

IN THE SW 1/4 OF SEC. 21, T25N, R14E, MDM

County of PLUM, S

Brief Legal Description PARCEL 2 OF 5 PM 9



CORNER TYPE

Government Corner Control COORDINATES
(Optional)Meander Property

N. _____

Rancho Other

E. _____

Date of Survey January 12, 2006

Zone _____ Datum _____

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points as shown and described on attached sketch and as shown on 5 PM 9
and Corner Record # 135.

A description of the physical condition of the monument as found and as set or reset:

Found points in record position and in good condition and set points in record
position as shown on attached sketch.


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in
conformance with the Land Surveyors' Act on January 12, 2006.Signed John W. Hamby L.S. 2843
John W. Hamby

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Feb 10th 2006 and
examined and filed February 21 2006.Signed R. Tom Shantz Title County Surveyor

County Surveyor's Comment _____




Note:
All Bearings and Distances are Record
and Measured per 5 PM 9

Found 5/8" Rebar with
Al. Cap LS 2843 (R2)


Found 5/8" Rebar with
Al. Cap LS 2843 (R2)

Set 5/8" Rebar with
Al. Cap LS 2843



LEGEND

- FOUND point as described
- SET Rebar with Aluminum Cap LS 2843
- Found Nothing, Set Nothing
- (R1) RECORD per 5 PM 9
- (R2) RECORD per Corner Record # 135



1" = 100'

05078

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571