


CORNER RECORD

Document Number 328

City of _____ County of Plumas, California

Brief Legal Description W 1/4 Section 26, T28N, R8E, MDM



CORNER TYPE

Government Corner Control

Meander Property

Rancho Other

Date of Survey 9/20/06

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88

Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found original Bearing Tree stump in poor condition. No trace of original GLO monument; destroyed by road. Also found original BT for E 1/4 Sec 26. That monument was destroyed by road work as well. The two BT's provided a good check. See sketch and photos.

A description of the physical condition of the monument as found and as set or reset: Reset the W 1/4 of Section 26 with a 5/8" rebar and wired brass LS tag to it - LS 5386. Raised mound, tagged two orig. BT's as shown and created new Bearing Tree.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on October 9 2006.

Signed Paul S. Pace P.L.S or R.C.E. No. PLS 5386



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Oct. 16th 2006

and examined and filed Nov. 9th 2006

Signed R. Tom Shantz P.L.S or R.C.E. No. 30515

Title Plumas Co. Engineer



County Surveyor's Comment Original GLO corners per William E. Hiester
Feb. 5, 1924 survey.

T28N, R8E MDM

