

## CORNER RECORD


Document Number

332

Portion of SW 1/4 Section 21, T. 23 N., R. 14 E., M.D.M.

County of Plumas, California

Brief Legal Description



## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey January 12, 2007

Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found T-Bars with tags RCE 5569 per 6 RS 68 which were labeled wrong on 9 PM 70  
on Southwest corner of Parcel 1 and found Aluminum Cap LS 2843 for South 1/4  
Corner of Section 21 as shown on 6 RS 68 and 9 PM 70 which was used to reestablish  
corners as shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset: Corners missing were  
set with 5/8" rebar with Aluminum Cap stamped LS 5620 as shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in  
conformance with the Land Surveyors' Act on January 26, 2007.


Signed John L. Owen L.S. 5620  
John L. Owen



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Feb. 1<sup>st</sup> 2007 and  
examined and filed \_\_\_\_\_ 2007.

Signed R. Tom Shantz Title County Surveyor




County Surveyor's Comment \_\_\_\_\_

All bearings and distances are record per 6 RS 68  
and 9 PM 70.

## LEGEND

- FOUND point as described
- SET 5/8" rebar with Aluminum Cap LS 5620



Parcel 1, 9 PM 70  
Portion of the SW 1/4  
of Section 21,  
T. 23 N., R. 14 E., M.D.M.

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571