


CORNER RECORD

Document Number

355

Portion Section 14, T. 23 N., R. 11 E., M.D.M.

County of Plumas, California

Brief Legal Description Not a Part Existing parcel, 116 O.R. 204 per 11 PM 40

CORNER TYPE

Government Corner Control COORDINATES
(Optional)Meander Property

N. _____

Rancho Other

E. _____

Date of Survey 9-24-2007

Zone _____ Datum _____

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found corners per 11 PM 40 except that Not a Part Existing Parcel 116 OR 204 had
Plastic Caps and not Aluminum Caps as shown on 11 PM 40 as shown on attached
sketch.

A description of the physical condition of the monument as found and as set or reset: Most Westerly corner of
"Not a Part Existing Parcel 116 OR 204" was missing, set corner as shown on attached
sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in
 conformance with the Land Surveyors' Act on September 24, 2007.

Signed John L. Owen L.S. 5620
 John L. Owen



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Oct. 25th 2007 and
 examined and filed Oct. 30th 2007.

Signed R. Tom Shurtliff Title County Surveyor

County Surveyor's Comment _____




NOTE:

All bearings and distances are record per
11 PM 40, corner set in record position
as shown per 11 PM 40.



1" = 40'



LEGEND

- FOUND Plastic Cap LS 2843 not Aluminum Cap per 11 PM 40
- FOUND Rebar with Aluminum Cap LS 2843 per 11 PM 40
- Set 5/8" rebar with Aluminum Cap LS 5620