

<p>T29N R9E S7 S8 S18 S17 1977 CAF USFS</p> <p>CORNER No. 32 FD. A CAF CAP (MIS-STAMPED FOR T29N) IN A MOUND OF STONE. CORNER FALLS ON A STEEP NORTHWEST SLOPE, 60°± SOUTHEAST OF A ROAD. NO ACCESSORIES FD SCRIBED A 10" DOUGLAS FIR, S36°W, 22.5' "T26N R9E S18 BT" SCRIBED A 10" DOUGLAS FIR, S14°E, 15.6' "T26N R9E S7 BT"</p>	<p>1/4 S10 S15</p> <p>CORNER No. 38 FD. A 3/4" IRON PIPE MKD LS 3297 IN A MOUND OF STONE PER 4 R/S 139. CORNER FALLS ON A MODERATE NORTH SLOPE. NO ACCESSORIES FOUND OR TAKEN</p>	<p>CORNER NOTES HB = HEALED BLAZE VS = VISIBLE SCRIBING BCIP = BRASS CAPPED IRON PIPE USFS DRIVE IN MON. = 3-1/4" ALUM CAP ON A 5/8" ALUM. ROD</p>	<p>MS3110 PQM PL 6</p> <p>LS 4753 CORNER No. 56 FD. A MOUND OF STONE. SET A USFS DRIVE IN MONUMENT AND REBUILT MOUND. CORNER FALLS ON A MODERATE SOUTH SLOPE IN A MINED AREA. SCRIBED A 10" SUGAR PINE, S53°E, 17.1' "PL 6 MS3110 BT" SCRIBED AN 8" PONDEROSA PINE, N8°E, 13.3' "PL 6 MS3110 BT"</p>	<p>LS CORNER No. 64 4647 FD. A CAPPED 1/2" REBAR PER 12 R/S 39. CORNER FALLS ON SOUTH EDGE OF ROAD.</p>				
<p>T26N R9E 1/4 S8 S17 LS 4753 2008</p> <p>CORNER No. 33 SET A USFS DRIVE IN MONUMENT IN A MOUND OF STONE FROM WHICH A CAF 3/4" IRON PIPE BEARS S62°W, 8.0'. CORNER FALLS ON A MODERATE NORTHEAST SLOPE IN TIMBER. SCRIBED A 9" WHITE FIR, S56°W, 14.7' "1/4 S7 BT" SCRIBED AN 8" WHITE FIR, N11°W, 34.0' "1/4 S8 BT"</p>	<p>T26N R9E 1/4 S11 S14 LS 3346 1994</p> <p>CORNER No. 40 FD. A 3 1/4" ALUM CAP ON A 1/2" STEEL BAR PER 10 R/S 84. CORNER FALLS ON A WEST SLOPE. FD. A 6" BLACK OAK, S58°E, 28.2' -HB REC. A 6" OAK, S58°E, 28.2' (10 R/S 84) FD. A 6" BLACK OAK, N38°E, 26.4' -HB REC. A 6" OAK, N38°W, 26.4' (10 R/S 84)</p>	<p>MS1023 X S11</p> <p>MS4315 CORNER No. 49 SET A USFS DRIVE IN MONUMENT IN A MOUND OF STONE CORNER FALLS AT THE TOP OF A NORTH SLOPING SPUR EAST OF A LOGGING OPERATION. NO ACCESSORIES AVAILABLE</p>	<p>MS3110 EL 5</p> <p>LS 4753 CORNER No. 57 FD. ORIG BEARING TREE SET A USFS DRIVE IN MONUMENT IN A MOUND OF STONE. CORNER FALLS ON A STEEP, ROCKY NORTHEAST SLOPE. FD. A 27" SUGAR PINE, N58 1/2°W, 19.0' -HB REC. A 20" SUGAR PINE, N58 1/2°W, 19' (GLO) SCRIBED A 10" DOUGLAS FIR, N86°E, 13.9' "EL 5 MS3110 BT"</p>	<p>LS CORNER No. 65 4647 FD. A CAPPED 1/2" REBAR PER 12 R/S 39. CORNER FALLS IN LAWN OF HOME.</p>				
<p>T26N R9E S8 S9 S17 S16 CAF 1964</p> <p>CORNER No. 34 FD. A 3" CAF CAP IN A MOUND OF STONE PER BLM. CORNER FALLS ON A FLAT IN HEAVY TIMBER. FD. A 20" WHITE FIR, N67°W, 18.8' -HB REC. A 32" DOUGLAS FIR, N65 1/2°W, 28 LKS (BLM) FD. A 14" WHITE FIR, S15°E, 7.9' -HB REC. AN 11" WHITE FIR, S15°E, 12 LKS (BLM) FD. AN 8" WHITE FIR, N25°E, 13.2' -HB REC. AN 8" SUGAR PINE, N25°E, 20 LKS (BLM) FD. A 16" DOUGLAS FIR, S70°W, 10.6' NO REC.</p>	<p>T26N R9E 1/4 S9 S16 LS 4753 2008</p> <p>CORNER No. 41 FD. A 3/4" IRON PIPE IN A MOUND OF STONE PER 10 R/S 84 (NO TAG). CORNER FALLS ON A STEEP WEST SLOPE IN DENSE TIMBER, 60°± WEST OF A SKID ROAD. FD. A 9" OAK, S1°E, 9.9' REC. AN 8" OAK, SOUTH, 10.5' (10 R/S 84)</p>	<p>MS 4315 X 3 MS 6242 NE</p> <p>MS 4753 CORNER No. 50 FD. A USFS DRIVE IN MONUMENT IN A MOUND OF STONE PER 13 R/S 122. CORNER FALLS ON A MODERATE NORTHEAST SLOPE. FD. A 24" FIR STUMP, S22°E, 4.5' (PER 13 R/S 122) FD. A A 14" WHITE FIR, S73°W, 24.5' (PER 13 R/S 122)</p>	<p>MS3110 MS4376 EL 6 1 JBQM</p> <p>MS3110 CORNER No. 58 FD. A SCATTERED MOUND OF STONE. SET A USFS DRIVE IN MONUMENT AND REBUILT MOUND. CORNER FALLS ON AN OLD ROAD. SCRIBED AN 8" DOUGLAS FIR, N22°E, 13.3' "1 JBQM MS4376 BT" SCRIBED A 6" DOUGLAS FIR, S68°E, 24.6' "1 JBQM MS4376 BT"</p>	<p>T26N R9E CORNER No. 67 C1/4 S14 LS 3346 1994</p> <p>FD. A USFS DRIVE IN MONUMENT IN A MOUND OF STONE PER 10 R/S 84. CORNER FALLS ON A STEEP SOUTH SLOPE. FD. A 12" BLACK OAK, N25°W, 10.5' -HB REC. AN 8" BLACK OAK, N25°W, 11.6' (10 R/S 84) FD. A 19" INCENSE CEDAR, S39°W, 43.0' -VS REC. AN 18" CEDAR, S39°W, 43.0' (10 R/S 84)</p>				
<p>T26N R9E 1/4 S9 S16 LS 4753 2008</p> <p>CORNER No. 35 FD. A SPIKE IN A MOUND OF STONE. MONUMENT PER 12 R/S 39 NOT FOUND. SET A USFS DRIVE IN MONUMENT AND REBUILT MOUND. CORNER FALLS ON A STEEP SOUTH SLOPE IN SCATTERED TIMBER. SCRIBED A 15" DOUGLAS FIR, N61°E, 14.9' "1/4 S9 BT" SCRIBED A 6" DOUGLAS FIR, S12°E, 21.6' "1/4 S16 BT"</p>	<p>MS5775 T2</p> <p>LS 4753 CORNER No. 43 SET USFS DRIVE MON IN AMOS FROM ORIGINAL BT PER MS 5775. CORNER FALLS ON TOP OF A BERM IN A SKID ROAD. FD. A 12" PONDEROSA PINE, S54°W 12.6' -HB REC. 10" PINE S54°W 12.6'</p>	<p>MS2686 UQM2 1 IVQM LS4753 2008</p> <p>MS5775 CORNER No. 52 FD. A MOUND OF STONE. SET A USFS DRIVE IN MONUMENT AND REBUILT MOUND. CORNER FALLS ON A MODERATE EAST SLOPE, 70°± WEST OF A LOGGING ROAD. SCRIBED A 16" WHITE FIR, N2°W, 24.4' "PQM 2 MS3110 BT" SCRIBED A 9" WHITE FIR, S84°W, 14.6' "PQM 4 MS3110 BT"</p>	<p>MS 4376 PQM 3</p> <p>LS 4753 CORNER No. 59 FD. A MOUND OF STONE. SET A USFS DRIVE IN MONUMENT AND REBUILT MOUND. CORNER FALLS ON A STEEP EAST SLOPE. SCRIBED AN 8" INCENSE CEDAR, S11°E, 4.2' "3 PQM MS4376 BT" SCRIBED AN 8" DOUGLAS FIR, N10°E, 13.6' "3 PQM MS4376 BT"</p>	<p>SW 1/16 S14 LS 3346 1994</p> <p>CORNER No. 68 FD. A USFS DRIVE IN MONUMENT IN A MOUND OF STONE PER 10 R/S 84. CORNER FALLS ON A MODERATE SOUTH SLOPE. NO ACCESSORIES FOUND OR TAKEN</p>				
<p>COR W 3 S 9 1988 LS 5067</p> <p>CORNER No. 36 FD. A 2" ALUM. CAP ON A 1/2" REBAR IN A MOUND OF STONE PER PLUMAS COUNTY CORNER RECORD #74 FILED 1/5/93. FD. AN 8" INCENSE CEDAR, N13°W, 14.1' -VS REC. A 7" CEDAR, N13°W, 14.1' (C.R. OF 1/5/93) FD. A 10" BLACK OAK, N78°E, 8.6' -HB REC. A 10" OAK, N78°E, 8.6' (C.R. OF 1/5/93)</p>	<p>CORNER No. 44 FD. USFS DRIVE MON IN MOS PER 13 R/S 122</p>	<p>MS3110 PQM 8</p> <p>LS 4753 CORNER No. 53 FD. A MOUND OF STONE AND THE REMAINS OF A SCRIBED POST. SET A USFS DRIVE IN MONUMENT AND REBUILT MOUND. CORNER FALLS ON A STEEP SOUTHEAST SLOPE IN TIMBER. SCRIBED. A 7" PONDEROSA PINE, S22, 4.4' "PQM 4 MS3110 BT" SCRIBED A 10" PONDEROSA PINE, N85°E, 14.9' "PQM 4 MS3110 BT"</p>	<p>MS 4376 PQM 4</p> <p>LS 4753 CORNER No. 60 FD. A POST IN A MOUND OF STONE. SET A USFS DRIVE IN MONUMENT AND REBUILT MOUND. CORNER FALLS ON TOP OF A SMALL, SOUTH FACING SPUR. SCRIBED A 9" DOUGLAS FIR, S57°E, 14.4' "4 PQM MS4376 BT" SCRIBED A 10" PONDEROSA PINE, N70°W, 15.2' "4 PQM MS4376 BT"</p>	<p>SE 1/16 S14 LS 3346 1994</p> <p>CORNER No. 69 FD. A USFS DRIVE IN MONUMENT IN A MOUND OF STONE PER 10 R/S 84. CORNER FALLS ON A MODERATE SOUTH SLOPE. NO ACCESSORIES FOUND OR TAKEN</p>				
<p>T26N R9E S9 S10 S16 S15 1973</p> <p>CORNER No. 37 FD. A BLM BCIP IN A MOUND OF STONE. CORNER FALLS ON A STEEP EAST SLOPE, 100°± EAST OF A ROAD. FD. A 15" DOUGLAS FIR, N22°E, 20.5' -HB NO REC. FD. A 9" DOUGLAS FIR, S36°E, 17.8' -HB REC. A 7" DOUGLAS FIR, S36 1/2°E, 27 LKS (BLM) FD. A 10" SUGAR PINE, S84°W, 12.5' -VS REC. AN 8" SUGAR PINE, S84°W, 19 LKS (BLM) FD. A 9" DOUGLAS FIR, N35°W, 8.9' -VS REC. AN 11" DOUGLAS FIR, N30°W, 14 LKS (BLM)</p>	<p>CP1 MS1023 LS 4753 2008</p> <p>CORNER No. 46 FD. USFS DRIVE MON IN MOS PER 13 R/S 122</p>	<p>MS3110 PQM 7</p> <p>LS 4753 CORNER No. 55 FD. A MOUND OF STONE. SET A USFS DRIVE IN MONUMENT AND REBUILT MOUND. CORNER FALLS ON A GENTLE SOUTH SLOPE IN TIMBER. FD. A 32" PONDEROSA PINE, N5°E, 21.3' -HB REC. A 28" PITCH PINE, N5°E, 21' (GLO) SCRIBED A 9" INCENSE CEDAR, S23°E, 32.7' "PQM 7 MS3110 BT"</p>	<p>LS CORNER No. 61 4647</p> <p>FD. A CAPPED 1/2" REBAR PER 12 R/S 39. CORNER FALLS ON A FLAT.</p>	<p>CORNER No. 192 FD. A CAPPED 1/2" REBAR PER 12 R/S 39. CORNER FALLS ON A FLAT.</p>				
<p>MS3110 PQM 7</p> <p>LS 4753 CORNER No. 62 FD. A CAPPED 1/2" REBAR PER 12 R/S 39. CORNER FALLS ON A FLAT.</p>	<p>MS3110 PQM 7</p> <p>LS 4753 CORNER No. 63 FD. A CAPPED 1/2" REBAR PER 12 R/S 39. CORNER FALLS ON A FLAT.</p>	<p>MS3110 PQM 7</p> <p>LS 4753 CORNER No. 64 FD. A CAPPED 1/2" REBAR PER 12 R/S 39. CORNER FALLS ON A FLAT.</p>	<p>MS3110 PQM 7</p> <p>LS 4753 CORNER No. 65 FD. A CAPPED 1/2" REBAR PER 12 R/S 39. CORNER FALLS IN LAWN OF HOME.</p>	<p>MS3110 PQM 7</p> <p>LS 4753 CORNER No. 66 FD. A CAPPED 1/2" REBAR PER 12 R/S 39. CORNER FALLS IN DENSE TIMBER, 200°± NORTH OF A ROAD.</p>				
<p>USDA FOREST SERVICE PLUMAS NATIONAL FOREST "KEDDIE"</p> <p>IN SECTIONS 3, 8, 9, 10, 11, 15, 16 AND 22, T 26 N, R 9 E, MDM, AND IN SECTIONS 17 AND 20, T 27 N, R 9 E, MDM, IN THE UNINCORPORATED AREA OF PLUMAS COUNTY, STATE OF CALIFORNIA</p>								
<p>DEL TERRA INC. SURVEYING 1168 INDUSTRIAL ST. REDDING, CA 96002 PHONE (530) 241-8050</p>								
<p>DATE: NOVEMBER, 2008 SHEET 7 OF 8</p>								