



Facility Name: RIVER FRONT LOUNGE

FA ID# 2634

Pg 2 of 2

Date of Inspection: 5-12-10

OBSERVATIONS AND CORRECTIVE ACTIONS

PRE-OPENING INSPECTION.

35. ANSUL SYSTEM IN HOOD TO BE INSPECTED TO ASSURE PROPER FUNCTION & OPERATION.

DISHWASHER TO BE SUPPLIED W/ NEW SANITIZER TO ASSURE 50 PPM MIN DISINFECTION RESIDUAL.

45. ALL CRACKS, GAPS & HOLES IN WALLS AROUND PLUMBING TO BE PROPERLY SEALED.

- FACILITY APPROVED FOR OPERATION ONCE CONFIRMATION OF ANSUL INSPECTION PROVIDED TO E.H

Received by (Print)

Darrell Carlson

Title

Received by (Signature)

Darrell Carlson

Specialist (Print)

PAT SANDERS

Specialist (Signature)

[Signature]

Re-inspection Date: