

CORNER RECORD

Town
City of Greenville


Agency Index

453

Document Number

County of Plumas, California

Brief Legal Description 1 RS 105



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

COORDINATES (Optional)

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

Date of Survey March 31st, 2023

T. 26 N. R. 9 E., M.D.B. & M

PLS Act Ref.: 8765(d) 8771 8773 Other:

Corner/
Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):



SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on 4/25/23.

Signed Vernon H. Templeton P.L.S. or R.C.E. No. 4647

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 4/25/23


and examined and filed 5/18/23.

Signed R. Tom Shumate P.L.S. or R.C.E. No. 30515

Title County Surveyor

County Surveyor's Comment





LEGEND

- Found $\frac{1}{2}$ " pipe tagged L.S. 2702 except as noted per R/S 1-105
- Reset $\frac{1}{2}$ " rebar w/cap stamped L54647 at location of monuments per R/S 1-105 which was destroyed by fire.

Basis of Bearings is the southerly line of Main St. per R/S 1-105.