


CORNER RECORD

City of CRESCENT MILLS

Document Number _____

Brief Legal Description PARCEL 2 OF PARCEL MAP 2 PM 36

County of PLUMAS, California



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Replaced missing property corners due to logging operation

A description of the physical condition of the monument as found and as set or reset: Replaced missing 3/4" I.P. marked RCE 7294 with 3/4" I.P. with plastic plugs
LS 6373

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on July 27 1992.

Signed Hollis Lundy L.S. or R.C.E. Number 6373



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 7/29 1992 and examined
and filed 7/30 1992.

Signed R. Tom Shantz Title C. Engineer



County Surveyor's Comment _____

N 1/2 OF THE N.W. 1/4 OF S 25, T 26N, R 9E
MDM. PLUMAS COUNTY, CALIF.



- FOUND 3/4" IP WITH TAG RCE 18344
- FOUND 3/4" IP WITH TAG RCE 7294
- SET 3/4" IP WITH TAG LS 6373