


# CORNER RECORD

Document Number # 97

Portion of Section 6, T. 23 N., R. 14 E., M.D.M. County of Plumas, California

Brief Legal Description Southerly point on slope easement between Lots 70 & 71, Crocker Mountain Estates



## CORNER TYPE

Government Corner  Control

Meander  Property

Rancho  Other

Date of Survey October 10, 1994

## COORDINATES (Optional)

N. \_\_\_\_\_

E. \_\_\_\_\_

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found 1/2" I.P. for Southeast corner of Lot 71 and Southwest corner of Lot 70. no other points found on South lines of Lots 70 & 71, reestablished point between Lots 70 & 71 on slope easement line per 3 M 44. Point missing fell on steep cut bank.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with aluminum cap LS 2843 in record position.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on October 10, 1994.


Signed John W. Hamby L.S. 2843  
John W. Hamby




## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 11/2 1994 and  
examined and filed 11/2 1994.

Signed R. Tom Stanton Title \_\_\_\_\_



County Surveyor's Comment \_\_\_\_\_



Lot 70 & 71  
Crocker Mountain  
Estates