


## CORNER RECORD

Document Number 101Portion of Section 6, T. 23 N., R. 14. E., M.D.M. County of Plumas, CaliforniaBrief Legal Description NW corner Lot 74, Crocker Mountain Estates, 3 M 44

## CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey October 3, 1994

COORDINATES  
(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found 1/2" I.P. with Plastic Plug, barely legible, stamped RCE 13219 for Northwest corner of Lot 73 also found 5/8" rebar with plastic cap stamped LS 2843 which I accepted for the Southwest corner of Lot 74, from which I established the Northwest corner of Lot 74 between the two found corners.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with aluminum cap stamped LS 2843 for Northwest corner of Lot 74 which is also the Southwest corner of Lot 73.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on October 10, 1994.


Signed John W. Hamby L.S. 2843  
 John W. Hamby



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 11/2 1994 and  
 examined and filed 11/2 1994.

Signed Tom Schmitz Title \_\_\_\_\_



County Surveyor's Comment \_\_\_\_\_

Found 1/2" I.P. with  
Plastic Plug RCE 13219  
per 3 M 44

