


CORNER RECORD

COUNTY OF PLUMAS T. 28 N R. 7E MDM MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT 6-23-95 19



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found old stump hole for original 18" Sugar Pine Section Corner tree. Matches distances south, north, & East.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 1/2" rebar tagged LS 3989 in stump hole & constructed stone mound.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

North 5284' to brass cap @ $\frac{11}{14} \frac{12}{13}$
 (1/4 corner not found)

14 13
 23 24

→ East 2645 to Fd 1/4 corner
 1/2" ip- capped LS 3989

↓ South 2630' to Fd. Cedar tree 1/4 corner
 tagged by LS 2322



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON June 26 1995

SIGNED: Land. J. NoyalL.S. or R.C.E. No.: LS 3989

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 6/26/95 AND EXAMINED AND FILED 1995

BY: R. Tom StantonTITLE: Co. EngineerDOCUMENT NO. 110

STATEMENT ON BACK OF SHEET

YES NO

