


CORNER RECORD

Document Number _____

Section 35, T. 24 N., R. 15 E., M.D.M.

County of Plumas

, California

Brief Legal Description SW right-of-way corner of Parcel 4, of 3 PM 33

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey September 8, 1995

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 1/2" I.P. tagged RCE 7294 at Southwest corner of Parcel 2 and Southeast corner of Parcel 4, from which I set the right-of-way point on the South line of Parcel 4.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with Aluminum Cap stamped LS 2843 in record position from found point shown above.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on September 8, 1995.

Signed John W. Hamby L.S. 2843
 John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 10/30 1995 and
 examined and filed 11/8 1995.


Signed R. Tom Slonter Title C.S. Surveyor



County Surveyor's Comment _____



1" = 200'



Parcel 4, of 3 PM 33

NE 1/4 of NW 1/4 Section 35
T. 24 N., R. 15 E., M.D.M.

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(916) 832-5571