


CORNER RECORD

Document Number

183

County of Yumas

, California

Brief Legal Description Lot 1 of 6 M 30 Portion Sec. 31 T.23N. R.17E.

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey August, 2000

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 1/2" Rebar with plastic cap marked RCE 22836 per 6 M 30 as shown

A description of the physical condition of the monument as found and as set or reset:

The Northeast corner and the Southwest corner of Lot 1 had been destroyed by road and utility construction. Reset corners with 5/8" Rebar with aluminum caps, LS 2843

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on August 11, 2000.

Signed John W. Hamby L.S. 2843
John W. Hamby

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received November 8th 2000 and examined and filed November 13th 2000.Signed R. Tom Shuster Title P.C. Engineer

County Surveyor's Comment _____



(R1) = Record per 6 M 30.

00121