

CORNER RECORD

Section 6, T.23N.R.14E. MDM

Document Number


184

County of Plumas

, California

Brief Legal Description

Lot 73 - Crocker Mountain Estates 3 M 44



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey Oct. 26, 2000

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
 Found 1/2" Iron Pipe with plastic caps at various Lot corners.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar with aluminum cap LS 2843 as a reference point to the Lot corner that was destroyed
 during road construction.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in
 conformance with the Land Surveyors' Act on October 26, 2000.

Signed John W. Hamby L.S. 2843
 John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Nov. 15 2000 and
 examined and filed Nov. 20 2000.

Signed R. Tom Sefante Title C. Surveyor

County Surveyor's Comment



