


## CORNER RECORD

Document Number 231

NW 1/4 SECTION 1, T.22 N., R.13 E., M.D.M.

County of PLUMAS, CaliforniaBrief Legal Description LOT 78 OF THE RIDGEWOOD SUBDIVISION UNIT No. 1, AT 5 M 46.

## CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey March 29, 2003

COORDINATES  
(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner- Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points as shown and described on attached sketch and as shown on 5 M 46.

A description of the physical condition of the monument as found and as set or reset:

Found points as described and in good condition. Points set as shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 1, 2003.

Signed John W. Hamby L.S. 2843  
 John W. Hamby



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 4-16 2003 and  
 examined and filed 4-28 2003.

Signed R. Tom Shantz Title Plumas County Surveyor



County Surveyor's Comment \_\_\_\_\_

LOT 79  
5 M 46

124.98'  
500' 50' 28'E

LOT 78  
5 M 46

126.44'  
N030131'E

LOT 77  
5 M 46

111.86'  
S110.00'W

$\Delta = 314'35"$   
R=531.77'  
L=30.00'

$\Delta = 5'32'28"$   
R=530.00'  
L=51.26'

$\Delta = 84'56'13"$   
R=19.96'  
L=29.59'

N87°00'00"E  
36.46'

30'

MAIN STREET

CEDAR RIDGE ROAD



1" = 30'

## LEGEND

- FOUND 1/2" Rebar & Plastic Cap LS 3297
- SET 5/8" Rebar & Aluminum Cap LS 2843
- Nothing found or set

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571