


CORNER RECORD

Document Number 260

IN THE SW1/4 SEC 36, T23N.,R16E.,M.D.M. County of PLUMAS, California

Brief Legal Description LOT 2 FRENCHMAN SUBDIVISION 3 M 22



CORNER TYPE

Government Corner Control Meander Property Rancho Other Date of Survey DECEMBER, 2003COORDINATES
(Optional)

N. _____

E. _____

Zone _____ Datum _____

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND POINTS AS SHOWN AND DESCRIBED ON ATTACHED SKETCH AND AS SHOWN ON

3 M 22.

A description of the physical condition of the monument as found and as set or reset:

FOUND POINTS AS DESCRIBED AND IN GOOD CONDITION. POINTS SET AS SHOWN ON
ATTACHED SKETCH.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in
conformance with the Land Surveyors' Act on December 10, 2003.Signed John W. Hamby L.S. 2843
John W. Hamby


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-15- 2004 andexamined and filed 2/6/04 2004.Signed R. Tom Smith Title Engineer

County Surveyor's Comment _____



1" = 100'



LEGEND

- FOUND point as described
- SET 5/8" Rebar & Aluminum Cap LS 2843
- NOTHING Found or Set

All data is record and measured unless indicated

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571