

CORNER RECORD

Document Num.


283

Section 10, T.22N., R.13E., M.D.M.

County of Plumas

, California

Brief Legal Description Lot 26, Iron Horse Subdivision per 3 M 110



CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey Dec. 13, 2004

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points indicated on attached sketch in good condition and in record position.

Set 5/8" rebar with Aluminum cap stamped LS 2843 at location for missing corner.

A description of the physical condition of the monument as found and as set or reset:

see above

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on December 13, 2004.

Signed J.W. Hamby L.S. 2843
John W. Hamby

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Feb. 18, 2005 and
examined and filed March 24th, 2005Signed R. Tom Shantz Title Engineer
Plumas County


County Surveyor's Comment _____

- FOUND point as described
- SET 5/8" Rebar & Aluminum Cap LS 2843

(R1) RECORD per 3 M 110.
(M) Measured



APN 126-043-005



LOT 26
IRON HORSE RANCHO SUB.

Book 3 Maps page 110
Portion Sec. 10, T.22N.R.13E. MDM
Plumas County, Calif
Scale 1"=100' December, 2004

04344

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571