

CORNER RECORD


Document Number

288

Section 36, T.23N. R.1E. M.D.M.

County of Lumas

, California

Brief Legal Description Portion Block 53 Second North Addition to Portola Townsite
Book A Maps page 30, and as shown on 9 PM 140

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey May 20, 2004

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found points as shown and described on attached sketch and as shown on 9 PM 140
and Corner Record 204.

A description of the physical condition of the monument as found and as set or reset:

Found points as described and in good condition. Points set as shown on
attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in
conformance with the Land Surveyors' Act on May 20, 2004.Signed John L. Owen L.S. 5620
John L. Owen

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received April 8th 2005 and
examined and filed May 31, 2005.Signed R. Tom Stauffer Title Engineer

County Surveyor's Comment

- FOUND Rebar with Plastic Cap LS 2843 per 9 PM 140.
- FOUND 5/8" Rebar & Aluminum Cap LS 5620 per CR 204.
- FOUND point as described per 9 PM 140
- ☒ SET 5/8" Rebar with Aluminum Cap LS 5620

(R1) RECORD per 9 PM 140
(R2) RECORD per A Maps 30

CR Corner Record



BLOCK 53
SECOND NORTH ADD.
TO PORTOLA TOWNSITE

BOOK A PAGE 30
PORTOLA PLUMAS Co. CALIFORNIA
Scale 1" = 50" May, 2004

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571