


## CORNER RECORD

Document Number 293

Portion Sec. 35 T.23N.R.13E &amp; Sec.2 T.22N.R.13E. MDM

County of Plumas, CaliforniaBrief Legal Description Parcel 2 per 4 PM 92

## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey July 2004

Elev. \_\_\_\_\_

Corner- Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found the points indicated of the attached sketch in good condition and in proper location.

A description of the physical condition of the monument as found and as set or reset:

Set point indicated which is a record location for a witness corner.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on July 15, 2004.

Signed John W Hamby L.S. 2843  
John W. Hamby

## COUNTY SURVEYOR'S STATEMENT


This Corner Record was received April 8<sup>th</sup> 2005 andexamined and filed May 31, 2005Signed R. Tom Hunter Title Engineer

County Surveyor's Comment \_\_\_\_\_

- FOUND 3/4" I.P. LS 3297
- SET 5/8" Rebar & Aluminum Cap LS 2843
- Record points (R1) nothing found or set
- FOUND 6" concrete Highway Monument
- (R1) RECORD per 4 PM 92.
- (M) Measured.



APN 125-040-025  
Scale 1"=200'



04149

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571