


## CORNER RECORD

Document Number 298

Portion NE 1/4 Section 36, T.23N.R.13E.

County of Plumas, CaliforniaBrief Legal Description Lot 8 Block 50 Second North Addition to Portola Townsite  
Book A Maps page 30.

## CORNER TYPE

Government Corner  Control Meander  Property Rancho  Other Date of Survey April 6, 2005COORDINATES  
(Optional)

N. \_\_\_\_\_

E. \_\_\_\_\_

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

*Found corners indicated in good condition, as shown on corner record # 200 AND corner record # 295.*A description of the physical condition of the monument as found and as set or reset:  
*see note above.*

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 6, 2005.


Signed John W. Hamby L.S. 2843  
John W. Hamby

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 8<sup>th</sup> 2005 and  
examined and filed August 8 2005.Signed R. Tom Shantz Title P.C. Engineer  
P.C. Surveyor

County Surveyor's Comment \_\_\_\_\_

- FOUND 5/8" rebar with cap LS 2843 per corner record 200.
- FOUND point as described
- FOUND 5/8" rebar with aluminum cap LS 2843 per corner record # 295
  - SET 5/8" Rebar & Aluminum Cap LS 2843 (R1) per corner record # 200
  - (R2) per A Maps 30



Lot 8 Block 50  
Second North Addition  
Portola Townsite  
A Maps 30

05036

Scale 1"=50'

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571