


CORNER RECORD

Document Number 299

Portion NE 1/4 Section 36, T.23N.R.13E. M.D.M.

County of PlumasBrief Legal Description Lots 22, 23, 24 Block 6, Northern Addition to Portola Townsite A Maps 32.

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey August, 2003

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found points indicated in good condition and in proper location, or as indicated.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" Rebar with Aluminum Caps at locations indicated.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on August, 2003.

Signed John W. Hamby L.S. 2843
John W. Hamby

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received May 19th 2005 and
examined and filed August 8 2005.Signed R. Tom Slanta Title County Surveyor


County Surveyor's Comment _____

- FOUND Rebar with Aluminum Cap LS 2843 per 9 PM 8
- SET 5/8" Rebar & Aluminum Cap LS 2843
- FOUND point as described not of record.
- (R1) RECORD per A Maps 32



A.P.N. 125-237-006

Scale 1"=40'



Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571