

CORNER RECORD

Document Number

302


D.K.

Portion Section 1 T.22N. R.13E. M.D.M.

County of Plumas

, California

Brief Legal Description Lot 9 Ridgewood Subdivision Unit No. 1 per 5 M 45.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey June 10, 2005

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
 Found corners indicated on attached sketch in good condition.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar with aluminum cap stamped LS 2843 as indicated between found corners.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on June 10, 2005.

Signed John W. Hamby L.S. 2843
 John W. Hamby



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7/11/05 2005 and examined and filed August 8 2005.

Signed R. Tom Shantz Title County Surveyor




County Surveyor's Comment

- FOUND 1/2" Rebar with Plastic Cap LS 3297. (R1)
- SET 5/8" Rebar & Aluminum Cap LS 2843
- (R1) RECORD per 5 m 45.



PONDEROSA CIRCLE

LOT 12



LOT 9 RIDGEWOOD SUBDIVISION

Portion Section 1 T.22N. R.13E., MDM
Portola Plumas County Calif.
Scale 1" = 50' June, 2005

05113

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571