

CORNER RECORD

Document Number


303

Portion Sec. 36, T.23N.R.13E. M.D.M.

County of

Plumas

, California

Brief Legal Description Lots 6 & 7 of a Resubdivision of a Portion of Second North Addition to Portola Townsite per Z M 2.

CORNER TYPE

Government Corner Control

N.

Meander Property

E.

Rancho Other

Zone

Date of Survey April 27, 2005

Datum

Elev.

COORDINATES
(Optional)Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Points found were on good condition, except the plastic caps shown were split and not legible.


A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar with Aluminum cap stamped LS 2843 at location indicated, between found monuments.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 27, 2005.

Signed John W. Hamby L.S. 2843
 John W. Hamby



8-01-05

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Aug. 2nd 2005 and
 examined and filed August 16 2005.

Signed R. Tom Stanton Title County Surveyor

County Surveyor's Comment



● FOUND Rebar with Aluminum Cap LS 2843 →


origin unknown,

● FOUND Rebar with Plastic Cap not legible → accepted as lot corners.

○ SET 5/8" Rebar & Aluminum Cap LS 2843

(R1) RECORD per 2 M 2

(M) Measured



PORTION BLOCK 48
RESUBDIVISION OF A
PORTION 2nd NORTH
ADDITION TO PORTOLA

BOOK 2 MAPS PAGE 2

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571