

## CORNER RECORD

Document Number

307

Portion Section 8, T. 22 N., R. 12 E., M.D.M.

County of Plumas, California

Brief Legal Description Lot 31, Plumas-Eureka Estates Unit No. 2, 4 M 96



## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey August 10, 2005

Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 1/2" rebars at Southeast corner of Lot 30 and P.C. North of Southeast corner of Lot 31 as shown in

Book 4 of Maps at page 96, Plumas County records, as shown in attached sketch.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with Aluminum Cap stamped LS 5620 in record position for Southeast corner of Lot 31 as shown in attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on August 10, 2005.

Signed John L. Owen L.S. 5620  
John L. Owen

## COUNTY SURVEYOR'S STATEMENT


This Corner Record was received Aug 10<sup>th</sup> 2005 and  
examined and filed October 25 2005.Signed Robert T. Hunter Title Plumas Co.  
Surveyor

County Surveyor's Comment \_\_\_\_\_



# Madora Lake Road

NOTE: Curve data are record  
per 4 M 96 and measured.



1" = 30'