

CORNER RECORD


309

COUNTY OF PlumasT. 28 NR. 7 E

Mount Diablo

MERIDIAN

CALIFORNIA

CORNER TYPE: GOVT CORNER MEANDER RANCHO CONTROL OTHER CORNER IDENTIFICATION - DATE OF VISIT August 23, 2005

Section 25

approximate location

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

The SW corner of Lot 5 was not found. The NW corner of Lot 5 and the SW corner of Lot 6 were used to re-establish the missing corner.


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 5/8" rebar and plastic plug stamped LS 4530

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____
 ZONE _____ ELEVATION _____ STATION _____
 NORTHINGS(Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

Bearings & distances are Record & Measured per 1 Maps 74.



- Indicates set 5/8" rebar & plug LS 4530.
- Indicates found 1 1/2" IP tagged LS 2322 per 1 Maps 74.

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER
 MY DIRECTION IN CONFORMANCE WITH THE LAND
 SURVEYORS ACT ON August 23, 2005.


SIGNED

L.S. or R.C.E. No.

L.S. 4530

05-03-62

SEAL



THE CORNER RECORD WAS RECEIVED 10/25/05
 AND EXAMINED AND FILED 10/25/05
 BY: Robert T. Hunter
 TITLE: Plumas Co. Engineer
 DOCUMENT NO. 309

