

## CORNER RECORD

31D

COUNTY OF Plumas

T. 27N

R. 8E

Mount Diablo

MERIDIAN


CALIFORNIA

CORNER TYPE: GOVT CORNER MEANDER RANCHO CONTROL OTHER 

CORNER IDENTIFICATION - DATE OF VISIT

November 24.

2004



Section 10

approximate location

Lot 4 of Block 6, 1 Maps 48.

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT 

## PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

The Northwesterly corner of Lot 4 was not found. The corner was reestablished by single proportion from the found and accepted iron bolt at the Southwesterly corner of Lot 4 and the found 1/2" rebar and plug tagged LS 3989 at the Northwesterly corner of Lot 5.


Found monuments accepted as lot corners. Record reference unknown or of no record.

## PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 5/8" rebar and plastic plug stamped LS 4530

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  STATIONS USED: NGS (USC & GS)  STATE  SECOND  COUNTY  OTHER  THIRD  STATION  ZONE  ELEVATION  NORTHINGS(Y)  STATION  EASTINGS(X)

## SKETCH: (Include reference tie or witness points, remarks and topo of area)



## SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER  
MY DIRECTION IN CONFORMANCE WITH THE LAND  
SURVEYORS ACT ON November 26, 2004.

SIGNED James Q. Eddy Jr.  
L.S. or R.C.E. No. L.S. 4530

04-03-45

SEAL



COUNTY SURVEYOR'S CERTIFICATE  
THE CORNER RECORD WAS RECEIVED 10/25/05  
AND EXAMINED AND FILED 10/25/05

BY: Robert T. Hunter  
TITLE: Plumas Co. Engineer  
DOCUMENT NO. 31D

