

## CORNER RECORD

Document Number 325

NE 1/4 Section 36, T.23N., R.13E., M.D.M.

County of Plumas, California

Brief Legal Description Lots 6, 7, &amp; 8, Block 5, Northern Addition to Portola, A Maps 32

X	

## CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey 5-24-06

COORDINATES  
(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
 Found controlling corners of Blocks 4 and 5 per 13 RS 55 from which I set corners  
 for outside boundary to Lots 6 through 8 in Block 5 as shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebars with  
 Aluminum Cap stamped LS 5620 for outside boundary to Lots 6 through 8 in Block 5  
 as shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in  
 conformance with the Land Surveyors' Act on July 10, 2006.


Signed \_\_\_\_\_ L.S. 5620  
 John L. Owen



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received July 19th 2006 and  
 examined and filed August 8 2006.

Signed R. Tom Shantz Title County Surveyor



County Surveyor's Comment \_\_\_\_\_

Note: All bearings and Distance  
are the same as shown on  
13 RS 55.

Found 3/4" I.P. tagged  
LS 2843 per 13 RS 55

Found 3/4" I.P. per corner  
record 242 as shown on  
13 RS 55

Found 3/4" I.P. open  
per 13 RS 55

Found 5/8" rebar  
with Aluminum cap  
LS 2843 per 13 RS 55

Found reset nail and copper disk stamped Caltrans per 13 RS 55