

# CORNER RECORD

Document Number 347  
 County of Plumas, California

City of n/a

Brief Legal Description 1/4 cor. of secs. 1 and 36, Tps27 & 28N, R10E, MDM, CA  
 (GCDB 640700 // Index A-23)

		CORNER TYPE		COORDINATES(Optional)	
<input type="checkbox"/>	<input type="checkbox"/>	Government Corner <input checked="" type="checkbox"/>	Control <input type="checkbox"/>	N. <u>n/a</u>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	Meander <input type="checkbox"/>	Property <input type="checkbox"/>	E. <u>n/a</u>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	Rancho <input type="checkbox"/>	Other <input type="checkbox"/>	Zone <u>n/a</u>	NAD27 <input type="checkbox"/> NAD83 <input type="checkbox"/>
				NAD83 Epoch <u>n/a</u>	<input type="checkbox"/>
				Elev. <u>n/a</u>	<input type="checkbox"/>
				Vert. Datum: <u>NGVD29</u>	<input type="checkbox"/> NAD88 <input type="checkbox"/>
				Meas. Units: <u>Metric</u>	<input type="checkbox"/> Imperial <input checked="" type="checkbox"/>

Date of Survey 6/15/2006

**Note:** This is a cor. recovery. No survey tie to distant cors. performed.

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Original corner set by James Barnham, under GLO Contract dated July 25, 1878, with Plat approval date of February 23, 1881, and no approval date for the Contract or Field Notes available from the BLM.

There is no record describing a remonumentation of this corner. A nearby survey, T28N, R10E, by Rodney D. Dawson, LS 3621, was recorded November 4, 1975, in Plumas County Record of Surveys Book 4, page 91 (4-RS-91)

Recovered original bearing tree remains:

A snag, 18 ins. diam., bears N. 5° W., 34 lks. dist., with fragmentary scribe mks. visible in open blaze.

Recovered bearing trees NOT OF RECORD:

A pine, 29 ins. diam., alive and healthy, bears S. 12° E., 52.6 ft. dist., with healed blaze.

A cedar, 35 ins. diam., alive and healthy, bears S. 84½° E., 29.1 ft. dist., with healed blaze.

A pine, 20 ins. diam., alive and healthy, bears N. 72½° W., 27.9 ft. dist., with healed blaze.

A description of the physical condition of the monument as found and as set or reset:

Found a 3/4 in. diam. iron pipe, with washer mkd. LS-3621 inserted, projecting 2 ins. above ground, firmly set in good condition, in a rock collar, 3 ft. base, to top.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors Act on April 23, 2007

Signed:   
 Ron C. Walter

L.S. No.: 6501




## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 20<sup>th</sup>, 2007 and examined  
 and filed June 25<sup>th</sup>, 2007

Signed: Tom Slauter P.L.S. or R.C.E. No.: RCE 30515

Title County Surveyor  
 County Surveyor Comment





(GCDB 640700 // Index A-23)



## NOTES

1. The True Meridian is the Basis of Bearing.

1/4 cor. of secs. 1 and 36  
Tps27 & 28N, R10E, MDM, CA  
**Wallowa Associates - Ron Walter, LS**  
 April 23, 2006

## LEGEND



Recovered monument NOT OF RECORD.



Recovered original bearing tree remains.



Recovered bearing tree NOT OF RECORD.