


CORNER RECORD

Document Number 359

Section 34, T. 23 N., R. 13 E., M.D.M.

County of Plumas, California

Brief Legal Description Lot 8, 6 RS 112, Grizzly Lake Resort Improvement District

CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey October, 23, 2007

Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Southeast corner of Lot 8 missing used Northeast corner and Southwest corner of Lot 8 to set Southeast corner of Lot 8 in record position as shown on attached sketch.A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with Aluminum cap stamped LS 5620 as shown on attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on October 26, 2007.


Signed John L. Owen L.S. 5620
John L. Owen

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Oct. 26th 2007 and
examined and filed Dec. 12th 2007.Signed R. Tom Shumter Title County Surveyor
RCE 30515

County Surveyor's Comment _____





Lot 8, 6 RS 112
 Grizzly Lake Resort
 Improvement District

Hamby Surveying Inc.
 P.O. Box 1209
 Portola, CA 96122
 (530) 832-5571