


## CORNER RECORD

Document Number 369

Portion Section 34, T. 23 N., R. 13 E., M.D.M.

County of Plumas, California

Brief Legal Description Lots 22, 23 &amp; 24, 3 M 7, Delleker Subdivision, Unit 2



## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey \_\_\_\_\_

Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found 1/2" I.P. with weathered or missing plastic caps as shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" rebar with Aluminum Cap stamped LS 5620 as shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on March 26, 2008.

Signed John L. Owen L.S. 5620  
John L. Owen


5-22-08

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 6/12 2008 and  
examined and filed July 16, 2008.Signed R. Tom Stanton Title County Surveyor

County Surveyor's Comment \_\_\_\_\_

*measured* NOTE: All bearings and distance shown are  
and record per 3 M 7, Delleker Subdivision  
Unit NO. 2.



## LEGEND

- FOUND point as described
- SET 5/8" rebar with Aluminum Cap LS 5620