

CORNER RECORD

Document Number

371


T. 23 N., R 14 E. S. 17 MDM

County of

Plumas

, California

Brief Legal Description Lot 184 Grizzly Ranch Unit 4, 9 M 139



CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey July 25, 2008

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found Rebar with Aluminum or Plastic Cap, LS 2843, at locations shown on attached sketch.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" Rebar with Aluminum Cap, LS 5620, on line 2' Northwesterly of true corner position of Westerly Corner common to Lots 184 & 185 as shown on attached sketch.

True corner position falls in electric cabinet. Aluminum Cap is stamped W.C. 2'.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on August 25, 2008.

Signed John L. Owen L.S. 5620
John L. Owen

8-25-08

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Sept. 2, 2008 and
examined and filed Sept. 9, 2008.Signed R. Tom Shultz Title County Surveyor

County Surveyor's Comment _____

All Bearings and Distances are Record and Measured per 9 M 139

