

## CORNER RECORD

Document Number

379

Portion of Section 10, T. 22 N., R. 13 E., M.D.M. County of Plumas, California  
 Brief Legal Description Lot 102, Iron Horse Rancho Subdivision, 3 Maps 110

	x
10	

## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)Meander  Property 

N. \_\_\_\_\_

Rancho  Other 

E. \_\_\_\_\_

Date of Survey December 2, 2008

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

✓ Found 3/4" I.P. at NW corner Lot 103 and SW & SE corners Lot 101 in good condition.  
 ✓ Found 1/2" square head Bolt at NE corner of Lot 102 in good condition.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" Rebar with Aluminum Cap, LS 5620, at NW corner of Lot 102.

Set 5/8" Rebar with Aluminum Cap, LS 5620, marked RW 20 102, on Road Easement line at locations shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on December 4, 2008.

Signed John L. Owen L.S. 5620  
 John L. Owen




12-04-08

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Dec. 8<sup>th</sup> 2008 and  
 examined and filed Dec. 22, 2009.

Signed Robert T. Hunter Title County Surveyor  
 Robert T. Hunter RCE 30515  
 Expires 3/31/2010  
 County Surveyor's Comment \_\_\_\_\_





## LEGEND

- FOUND 1/2" square head Bolt accepted as set per 3 M 110
- FOUND 3/4" I.P., Open, accepted as set per 3 M 110
- SET 5/8" Rebar with Aluminum Cap LS 5620