


## CORNER RECORD

Document Number 3817

S. 10 &amp; 11, T. 22N, R. 13E, M.D.M.

County of Plumas

, California

Brief Legal Description Lot 54, Iron Horse Rancho, 3 Maps 110

## CORNER TYPE

Government Corner  Control COORDINATES  
(Optional)

N. \_\_\_\_\_

Meander  Property 

E. \_\_\_\_\_

Rancho  Other 

Zone \_\_\_\_\_ Datum \_\_\_\_\_

Date of Survey November 9, 2010

Elev. \_\_\_\_\_

Corner— Left as found  Found and tagged  Established  Reestablished  Rebuilt 

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 3/4" I.P. at Northwest corner of Lot 54 and Found 1/2" diameter

by 1" square head bolt at Northeast corner of Lot 55 both in good condition.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar with aluminum cap LS 5620 in record position per 3 Maps 110 as shown on attached sketch.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on November 16, 2010.

Signed John L. Owen L.S. 5260  
John L. Owen

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Dec. 2<sup>nd</sup> 2010 andexamined and filed January 5 2010.Signed R. Tom Shantz Title County Surveyor

County Surveyor's Comment \_\_\_\_\_

Bearings and Distances are Record and  
Measured per 3 Maps 110.



LEGEND

- FOUND 1/2" diameter by 1" square head bolt
- FOUND 3/4" I.P. wood plug, no tag
- SET 5/8" Rebar with Aluminum Cap LS 5620