

CORNER RECORD

Document Number

405


Section 15, Township 22 N., Range 13 E., M.D.M.

County of

Plumas

, California

Brief Legal Description Lot 280 Gold Mountain, Unit 11, Book 8 of Maps at Page 107-111



CORNER TYPE

Government Corner Control COORDINATES
(Optional)

N. _____

Meander Property

E. _____

Rancho Other

Zone _____ Datum _____

Date of Survey December 7, 2013

Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 5/8" rebar with Aluminum Cap stamped LS 2843, in good condition, at locations

shown on the attached sketch.

A description of the physical condition of the monument as found and as set or reset:

Set 5/8" rebar with Aluminum Cap stamped LS 8463, in record position shown on 8 M 108,
as shown on the attached sketch.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in
conformance with the Land Surveyors' Act on December 7, 2013.Signed Steven A. Alfred L.S. 8463
Steven A. Alfred

COUNTY SURVEYOR'S STATEMENT

12/7/13

This Corner Record was received December 20 2013 and
examined and filed January 21 2014.Signed R. Tom Shantz Title County Surveyor

County Surveyor's Comment _____

The Basis of Bearings of this sketch is identical to that shown on 8 M 107 - 111, Plumas County records.

