


# CORNER RECORD

City of QUINCY  
Brief Legal Description THE SE 1/4 OF SECTION 4 22, T24N, R8E, M.D.-01.

Document Number 410

County of PLUMAS, California



## CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 8/26/14

## COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

IN PARCEL 3 OF 7PM94, FOUND A 1/2" REBAR WITH PLASTIC CAP MARKED LS 3297 AT THE NORTHERLY CORNER OF A LINE WHICH BEARS NO° 30' 20" W 141° 51' FT.

A description of the physical condition of the monument as found and as set or reset: FOUND RUSTY REBAR AND CRACKED PLASTIC CAP WAS REPLACED WITH A 5/8" X 24" REBAR WITH A 1 1/2" ALUMINUM CAP STAMPED # LS. 6569. DISCARDED OLD REBAR AND CAP.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on AUGUST 26 2014

Signed John P. Schmidt L.S. or R.C.E. Number L.S. 6569



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 17 2014 and examined

and filed November 3 2014

Signed R. Tom Shute Title Co Surveyor



County Surveyor's Comment \_\_\_\_\_

