

# CORNER RECORD


Agency Index  
Document Number

428

City of Greenville County of Plumas, California

Brief Legal Description 5516 Diamond Mtn. Rd. A.P.N.:004-250-007

Parcel 15 2 MAPS 64



## CORNER TYPE

- Government Corner
- Control
- Meander
- Property
- Rancho
- Other

## COORDINATES (Optional)

N. \_\_\_\_\_ E. \_\_\_\_\_  
Elevation \_\_\_\_\_  
Units \_\_\_\_\_ Metric \_\_\_\_\_ U.S. Survey Foot \_\_\_\_\_  
Horizontal Datum \_\_\_\_\_  
Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_  
Vertical Datum \_\_\_\_\_  
 Complies with Public Resources Code §§8801-8819  
 Complies with Public Resources Code §§8890-8902

Date of Survey June 27, 2018

T 27 N, R 11 E Sec. 31

PLS Act Ref.:	<input checked="" type="checkbox"/> 8765(d)	<input type="checkbox"/> 8771	<input type="checkbox"/> 8773	<input type="checkbox"/> Other:
Corner/ Monument:	<input type="checkbox"/> Left as found	<input type="checkbox"/> Established	<input type="checkbox"/> Rebuilt	<input type="checkbox"/> Pre-Construction
	<input type="checkbox"/> Found and tagged	<input checked="" type="checkbox"/> Reestablished	<input type="checkbox"/> Referenced	<input type="checkbox"/> Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):


NW corner of Parcel # 15 Carroll Acres Subdivision as shown on 2M64. Found rusted out 1" iron pipe 12.8ft. out of record position for this corner. Travis Mitchell, the landowner of Parcel # 14 said he found the pipe laying on the ground and so he placed it in the position where he thought it should go. I discarded the the old I.P. and replaced it with a 24"x5/8" rebar with a 1 1/2" aluminum cap stamped LS 6569, set 14" in the ground.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on June 27, 2018

Signed

 P.L.S. or R.C.E. No. PL5.6569



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 28, 2018

and examined and filed Aug. 15, 2018

Signed  P.L.S. or R.C.E. No. 30515

Title Plumas County Surveyor

County Surveyor's Comment

This "corner Record" shows material discrepancies between the monuments found and a Record of Survey should be performed to show his interpretation as to where this corner should be located.





FOUND 1" I.P.  
PER RECORD

No CAP

NOT FOUND

13

SET 24" x 58"  
REBIRZ ON LINE

160 94  
160 94  
(23255)

160 94  
160 94  
(23255)

160 94  
161 02  
(23255)

393 47  
393 43  
(23255)

S 1°19' E

14

15

FOUND 1" I.P.  
PER RECORD

No CAP

16

FOUND 1" I.P.  
PER RECORD

No CAP

CARROLL ACRES SUBDIVISION  
UNIT NO. 1

2 M 64