

CORNER NOTES

CORNER KEY
CAP MARKINGS

ABBREVIATIONS:

ACAP - Aluminum Capped Aluminum Pipe, BT - Bearing Tree
 BCIP - Brass Capped Iron Pipe, PP - Ponderosa Pine
 AMOS - A mound of Stones, USFS - Forest Service
 BLM - Bureau of Land Management, DF - Douglas Fir
 SP - Sugar Pine, LO - Live Oak, BO - Black Oak
 IC - Incense Cedar (bearing tree markings in parenthesis)

(1) T27N R10E
 S21|S22
 S28|S27
 LS 4790
 1991
 Found original BTs, 21" PP, S60°W 134.6' (healed blaze)
 21" IC, N57°W, 31.7' (healed blaze)
 Set USFS ACAP in AMOS and marked new BTs
 5" IC, N1°E, 27.3' (T27NR10ES22 BT)
 5" WF, S20°E, 26.8' (X BT)
 Corner is located on steep SW slope 4.3 Ch. E/O gulch, drains NW

(2) T27N R10E
 1 1/4 S22
 1/4 S27
 LS 4790
 1991
 No original evidence found. At single proportion position
 Set ACAP in AMOS and marked new BTs
 15" DF, S19°30'E, 20.7' (1/4S27 BT)
 7" LO, N46°W, 11.1' (1/4S22 BT)

(3) T27N R10E
 S22|S23
 S27|S26
 LS 4790
 1991
 Found original 60x45x36" boulder, 40' NW/O creek, flows SW.
 Found 3/4" IP tagged LS 2322 lies 2' West, not of record.
 Set USFS rock cap atop boulder and marked new BTs
 4" PP, N47°E, 11.2' (X BT)
 4" PP, S30°W, 17.3' (X BT)
 3" PP, N55°W, 24.3' (X BT)
 4" Willow, S29°E, 16.4' (X BT)

(4) W 1/16 S23
 1/16 S26
 LS 4790
 1991
 Set USFS ACAP in AMOS and marked BTs
 5" IC, N70°E, 13.1' (W1/16S23 BT)
 6" IC, S37°E, 9.9' (W1/16S26 BT)

(5) T27N R10E
 1 1/4 S23
 1/4 S26
 1975
 BLM
 Found 1975 BLM BCIP in AMOS and BTs
 26" PP, S16°E, 28.4' (healed blaze)
 24" Fir, N32°W, 13.2' (healed blaze)

(6) T27N R10E
 S23|S24
 S26|S25
 1975
 BLM
 Found 1975 BLM BCIP in AMOS and BTs
 12" SP, S45°E, 44.9' (healed blaze)
 15" DF, S32°W, 20.5' (healed blaze)
 44" PP, N69°W, 48.2' (healed blaze)
 23" IC, N32°E, 30.4' dead & down
 Marked new BT, 5" DF, N17°E, 36.1' (X BT)

(7) T27N R10E
 1/4 S28|S27
 LS 4790
 1991
 No original evidence found. At single proportion position
 Set USFS ACAP in AMOS and marked BTs
 8" WF, S37°W, 3.2' (1/4S28 BT)
 15" WF, East, 1.8' (1/4S27 BT)

(8) T27N R10E
 1/4 S27|S26
 LS 4790
 1991
 No original evidence found. At single proportion position
 Set USFS ACAP in AMOS and marked BTs
 6" DF, N38°W, 9.2' (1/4S27 BT)
 6" DF, N70°30'E, 10.9' (1/4S26 BT)
 Corner is located 60 S/O draw, drains NE

(9) W 1/16 C—C
 S26
 LS 4790
 1991
 Set USFS ACAP in AMOS and marked BTs
 16" PP, S33°E, 22.2' (CW1/16S26 BT)
 13" DF, S40°W, 32.6' (CW1/16S26 BT)
 Corner is located 30' SW/O road along Cook's Creek

(10) E 1/16 C—C
 S 26
 LS 4790
 1991
 Set USFS ACAP in AMOS and marked BTs
 10" DF, N6°E, 14.9' (CE1/16S26 BT)
 8" DF, S88°E, 11.9' (CE1/16S26 BT)
 Corner is located on SW slope

(11) T27N R10E
 1/4 S26|S25
 LS 4790
 1991
 Found original 28x18x6" stone marked 1/4 in AMOS
 Found original BTs 18" IC, S20°E, 29.7' (healed blaze)
 20" DF, N70°W, 12.5' dead & down
 Set USFS ACAP in AMOS, buried stone and marked new BT
 18" PP, N75°W, 19.1 (1/4S26 BT)

(12) S1/16 C
 S27
 LS 4790
 1991
 Set USFS ACAP in AMOS and marked BTs
 8" SP, N21°W, 7.4' (CS1/16S27 BT)
 8" DF, S67°E, 8.5' (CS1/16S27 BT)
 Corner is located 60' N/O spur ridge, falls E

(13) T27N R10E
 S1/16 S26
 LS 4790
 1991
 Set USFS ACAP in AMOS and marked BTs
 6" DF, S71°W, 14.6' (S1/16S27 BT)
 5" DF, S41°E, 10.4' (S1/16S26 BT)
 Corner is located 250' S/O knob on S Slope

(14) T27N R10E
 S28|S27
 S33|S34
 1975
 BLM
 Found 1975 BLM BCIP in AMOS and BTs
 26" original PP snag, N80°W, 9.9'
 6" WF, N47°E, 37.0' (healed blaze)
 12" DF, S77°E, 10.6' (healed blaze)
 Corner is located on steep E slope 60' N/O ravine, drains E & 400' E/O road 28N32, bears NE

(15) T27N R10E
 1 1/4 S27
 4 S34
 LS 4790
 1991
 No original evidence found. At single proportion position
 Set USFS ACAP in AMOS and marked BTs
 6" WF, N56°E, 23.3' (1/4S27 BT)
 6" WF, S11°E, 29.5' (1/4S34 BT)

(16) E 1/16 S27
 S33|S34
 LS 4790
 1991
 Set USFS ACAP in AMOS and marked BTs
 15" DF, S25°E, 15.2' (E1/16S34 BT)
 16" DF, N81°E, 9.8' (E1/16S27 BT)

(17) T27N R10E
 S27|S26
 S34|S35
 1975
 BLM
 Found 1975 BLM BCIP in AMOS and BTs
 37" original P snag, N67°30'W, 23.1'
 P stump remains, S9°30'W, 81.2'
 16" WF, S70°W, 53.5' (healed blaze)
 14" WF snag, S55°E, 24.4'
 20" WF, S61°E, 19.8' (healed blaze)

(18) T27N R10E
 1 1/4 S26
 4 S35
 LS 4790
 1991
 Found 5/8" rebar with AC marked LS 2670, not of record.
 Accepted as perpetuation and replaced with USFS ACAP in AMOS and marked new BTs
 11" PP, N74°W, 6.3' (1/4S26 BT)
 9" PP, S20°W, 28.7' (1/4S35 BT)

(19) E 1/16 S26
 S33|S35
 LS 4790
 1991
 Set USFS ACAP in AMOS and marked BTs
 8" IC, N23°E, 13.0' (E1/16S26 BT)
 10" IC, S44°E, 16.4' (E1/16S35 BT)

(20) T27N R10E
 S26|S25
 S35|S36
 LS 4790
 1991
 Found 5/8" rebar with AC marked LS 2670, per 6 RS 62.
 Found original 29" DF snag BT, N66°W, 96.4'
 Replaced rebar with USFS ACAP in AMOS and marked new BTs
 10" LO, N47°E, 15.6' (T27NR10ES25 BT)
 6" LO, S48°W, 25.3' (T27NR10ES35 BT)
 Set 1" brass tags marked LS 4790 on lava bluff S27°E, 17.3' and N32°W, 11.0' for Bearing Objects

(21) T27N R10E
 1/4 S33
 S34
 LS 4790
 1991
 No original evidence found. At single proportion position
 Set USFS ACAP in AMOS and marked BTs
 12" DF, N49°W, 43.6' (1/4S33 BT)
 6" LO, S35°E, 3.7' (1/4S34 BT)

(22) E 1/16 C—C
 S 34
 LS 4790
 1991
 Set USFS ACAP in AMOS and marked BTs
 9" IC, N39°W, 30.3' (CE1/16S34 BT)
 12" SP, S32°W, 27.8' (CE1/16S34 BT)

(23) T27N R10E
 1/4 S34
 S35
 LS 4790
 1991
 No original evidence found. At irregular boundary proportion position
 Set USFS ACAP in AMOS and marked BTs
 17" IC, S21°W, 37.4' (1/4S34 BT)
 7" BO, S48°E, 7.9' (1/4S35 BT)
 Corner is located on SE slope 35' N/O spring, flows E

(24) T27N R10E
 C1/4 S35
 LS 4790
 1991
 Set USFS ACAP in AMOS and marked BTs
 8" DF, N20°E, 7.6' (C1/4S35 BT)
 13" DF, S10°E, 13.6' (C1/4S35 BT)

(25) BURGESS LAND SURVEYS
 LS 4790
 1991
 Set 5/8" rebar with 2" AC in creek, flows NE.
 Set Reference Monuments on boundary lines
 South, 148' and West, 121'
 RP $\frac{1}{16}$ E 1/16 C—C
 S 35 LS 4790 1991

(26) T27N R10E
 1/4 S35 S36
 LS 4790
 1991
 Found 1" iron pipe with plastic plug marked LS 4643 in AMOS
 160' W/O fence corner per 6 RS 62. Accepted as one-quarter corner and replaced with USFS ACAP in AMOS. No BTs available

(27) T27N R10E
 S33|S34
 S4|S3
 T26N
 1970
 BLM
 Found 1970 BLM BCIP in AMOS and BTs
 10" BO, N27°E, 40 links (healed blaze)
 26" IC, S21°E, 54 links (scribes)
 6" IC, S74°W, 74 links (scribes)
 8" BO, N65°30'W, 29 links (healed blaze)
 12" LO, N22°W, 76 links (scribes)

(28) T27N R10E
 1 1/4 S34
 4 S33
 T26N
 LS 4790
 1991
 No original evidence found. At irregular boundary position
 Set USFS ACAP in AMOS and marked BTs
 3" PP, S64°W, 12.8' (X BT)
 19" IC, N40°W, 20.3' (1/4S34 BT)

(29) T27N R10E
 S34|S35
 S3|S2
 T26N
 1970
 BLM
 Found 1970 BLM BCIP in AMOS and BTs
 10 PP, N68°E, 28 links (healed blaze)
 54" IC snag, SE, 8' (healed blaze)
 33" IC snag, S48°W, 35 links (scribes)
 13" DF, N38°W, 29 links (healed blaze)
 Marked new BT, 5" DF, S23°E, 35.7' (X BT)

(30) T27N R10E
 1 1/4 S35
 4 S32
 T26N
 LS 4790
 1991
 Found 1" iron pipe with plastic plug marked LS 4643 per 6 RS 62. Accepted as perpetuation and replaced with USFS ACAP in AMOS and marked new BTs
 8" LO, S19°W, 15.9' (1/4S2 BT)
 10" DF, N14°W, 22.2' (1/4S35 BT)
 Corner is located 160' SW/O gulch, drains S30°E

(31) E 1/16 S35
 S2
 LS 4790
 1991
 Set USFS ACAP in AMOS and marked BTs
 7" LO, N61°E, 7.3' (E1/16S35 BT)
 7" PP, S1°W, 18.4' (E1/16S2 BT)

(32) Corner falls in Willit's cow pasture. Nothing found, nothing set, referenced per 6 RS 62

(33) T27N R10E
 1 1/4 S36
 4 S1
 T26N
 LS 4790
 1991
 Found 1" iron pipe with plastic plug marked LS 4643 per 6 RS 62 and 15x8x6" marked stone and BTs
 Oak remains N41°W, 97 links
 10" PP, N59°E, 16.5' (healed blaze)
 Replaced iron pipe with USFS ACAP in AMOS and marked BT
 6" BO, S67°W, 17.8' (1/4S1 BT)

RECORD OF SURVEY
for

ARCHIE WALKER & PLUMAS NATIONAL FOREST

Being Sections 26,27,34 & 35, T27N, R10E, MDM
 in the unincorporated territory of Plumas County, California

February 1992

Sheet 2 of 2

