



The Basis of Bearings of this map is the Southerly line of Lot 389 shown as S83°17'30"W, in Book 8 of Maps at page 141, Plumas County records.

Note: all bearings, distances and curve data shown are record per Gold Mountain Unit 16 "EAGLE FEATHER", 8 M 141, except those shown with (R1, R2 & R3) which are measured and record per Lot Line Adjustment Document 2000-4927, Document 2000-5417 and Document 2000-07966.

**LEGEND**

- FOUND Rebar with Aluminum Cap LS 2843
  - SET 5/8" Rebar with Aluminum Cap LS 2843
  - Nothing found or set
- (R1) Record per Document 2000-4927  
 (R2) Record per Document 2000-5417  
 (R3) Record per Document 2000-07135

Lots 301,384 thru 389 and 405 thru 407, Unit 16 "EAGLE FEATHER", 8 M 141

**RECORD OF SURVEY**  
 for  
**Gold Mountain Ranch, Inc.**

A portion of Section 22  
 T. 22 N., R. 13 E., M.D.M.  
 Plumas County ~ California  
 Scale 1" = 100' ~ November 2000

Hamby Surveying Inc.  
 P.O. Box 1209  
 Portola, CA 96122  
 (530) 832-5571