

① Found 1/2" rebar with Aluminum Cap stamped LS 2843 in mound of rock per 9 RS 147

② Found BLM Brass Cap monument, no accessories per 12 RS 134

③ Set Township corner by double proportion, stamped for Township Corner. No accessories available

④ Found 1/2" rebar with Plastic Cap LS 3297 at fence corner with K-tag

⑤ Found 1/2" rebar with Aluminum Cap LS 2843 stamped for corner

⑥ Found 1/2" rebar Cap missing, K-tag on fence post South 6' Set tag LS 2843

⑦ Corner not accessible due to time of year, used record position corner is 1/2" rebar with Aluminum Cap per (R1)

⑧ Set corner by single proportion, stamped for Section Corner No accessories available

⑨ Found 31/4" Aluminum Cap RCE 20257 1985 stamped for Section Corner, shown on 7 MS 81, Sierra County records.

⑩ Found 1/2" rebar with Aluminum Cap LS 2843 stamped for Section Corner, no accessories, per 6 RS 54, Sierra County records 7 MS 79 call point witness corner

⑪ Corner destroyed, Set new corner stamped for Section Corner from K-tag on fence post. K-tag S82°10'W, 82 links.

⑫ Found Sierra County Brass Cap stamped LS 2566 for Section Corner No accessories.

⑬ Found 5/8" rebar with Aluminum Cap stamped LS 2843 per 9 RS 34, no accessories.

⑭ Set Township corner by double proportion from Northwest corner of Section 31 and Southeast corner of Section 32, T.23N., R.16E., Southeast corner of Section 36 and Northwest corner of Section 2, T.22N., R.15E., stamped for corner. No accessories.

⑮ Section corner falls in Highway 70, used calculated position from found corners shown on R4, S00°30'06"W, 61.64' (S00°33'36"E, 61.64' R4)

⑯ Found 1/2" rebar with Aluminum Cap LS 2843 on North Line of State Highway 70, 60.87' Northerly of Southeast corner of Section 30, as shown per (R4)

⑰ Found 1/2" rebar with Aluminum Cap LS 2843 N00°26'58"E, 1.00' (N00°36'44"W, 1.00' R4) of North line of State Highway 70, 61.10' Northerly of the Southeast corner of Section 29 as shown per (R4)

⑱ Set corner on Township line between accepted fence corner for Northwest corner of Section 2 and Double proportioned Township Corner using North- South fence for Eastings

⑲ Set corner at accepted fence corner for Northwest corner of Section 2, and stamped for Section corner

⑳ Set corner at accepted fence corner for Northwest corner of Section 3, and stamped for Section corner

㉑ Corner computed on Township line by single proportion

㉒ Set corner on Township line by single proportion and stamped for corner

㉓ Set Section corner by double proportion and stamped for corner. No accessories available.

㉔ Set Section corner by double proportion and stamped for corner. No accessories available.

㉕ Computed Section corner by double proportion nothing set

㉖ Section corner set and stamped for corner by double proportion using Southwest corner of Section 33 and Northwest corner of Section 21 for northings and using Southwest corner of Section 30 and Southeast corner of Section 28 for Eastings. No accessories available

㉗ Section corner set and stamped for corner by double proportion using Southwest corner of Section 33 and Northwest corner of Section 21 for northings and using Southwest corner of Section 19 and Southeast corner of Section 22 for Eastings. No accessories available

㉘ Found Steel Pin in Stone corner at Intersection of fences to South and West, accepted for Section Corner, set tag LS 2843 No accessories available

㉙ Accepted fence corner for Section Corner, set corner stamped for Section Corner, no accessories available.

㉚ Found 1 1/2" Brass Cap N45°W, 2.83' from fence intersection, accepted intersection as Section corner Cap stamped as shown on sheet 1 not of record and not accepted as Section corner. No accessories available.

㉛ Section corner set and stamped for corner by Northing proportioned from Southwest corner of Section 27 and Northwest corner of Section 3 and using North- South fence for Eastings.

㉜ Section corner set and stamped for corner by double proportion using Southwest corner of Section 27 and Northwest corner of Section 3 for northings and using Southwest corner of Section 19 and Southeast corner of Section 22 for Eastings. No accessories available

㉝ Accepted fence corner for Section Corner, set corner stamped for corner, No accessories available.

㉞ Accepted fence corner for Section Corner, set corner stamped for corner, No accessories available.

RECORD OF SURVEY
for
U.S.D.A.

A portion of Sections 20, 21 and 28
T. 22 N., R. 15 E., M.D.M.
Plumas County ~ California
November, 2003

Hamby Surveying Inc.
P.O. Box 1209
Portola, CA 96122
(530) 832-5571

SHEET 3 OF 3