

T24N R7E 1/4 S32 S5 SET A USFS DRIVE IN MONUMENT N23W, 123.0' FROM THE CENTER OF ORIGINAL BEARING TREE. CORNER FALLS ON A STEEP WEST SLOPE, 130'± EAST OF A ROAD IN TIMBER. FD. A 73" PONDEROSA, S23E, 123.0' (FROM CENTER) -HB ORIGINAL BEARING TREE REC. A 70" PONDEROSA, S23E, 183 LKS (USFS COR. REC. BY J. EDGERTON 7-16-86) SCRIBED A 19" WHITE FIR, S73E, 17.6' "1/4 S5 BT" SCRIBED A 14" WHITE FIR, N10E, 42.0' "1/4 S32 BT"	E 1/16 C-C S7 LS 4753 2004 CORNER No. 10 SET A USFS DRIVE IN MONUMENT IN A MOUND OF STONE. FROM WHICH A 1-1/2" ALUM. CAP MARKED RCE 13528 ON A 1/2" REBAR MARKED RCE 13528 PER (1) BEARS N80°55'W, 24.75' - NOT ACCEPTED THIS SURVEY. CORNER FALLS IN A TIMBERED FLAT. SCRIBED A 28" WHITE FIR, S25W, 40.5' "CE 1/16 S7 BT" SCRIBED A 13" INCENSE CEDAR, N78W, 28.9' "CE 1/16 S7 BT"	T23N R7E 1/4 S7 S8 LS 4753 2004 CORNER No. 11 FD. A 3/4" IRON PIPE - OUT OF GROUND. SET A USFS DRIVE IN MONUMENT FROM BEARING TREES. CORNER FALLS ON A GENTLE NORTH SLOPE IN TAMARACK AND FIR ON THE SOUTH EDGE OF GRUBBS LOG ROAD. FD. A 24" SUGAR PINE, N62W, 29.7' -NO MKS VISIBLE REC. 5" SUGAR PINE, N62 1/4W, 45 LKS (GLO) FD. A 34" WHITE FIR, N47W, 67.3' -HB REC. A 16" WHITE FIR, N47W, 102 LKS (GLO)	T23N R7E 1/4 S7 S8 LS 4753 2004 CORNER No. 12 SET A USFS DRIVE IN MONUMENT IN A MOUND OF STONE. FROM WHICH A 1-1/2" ALUM. CAP ON A 1/2" REBAR MARKED RCE 13528 PER (1) BEARS N88°12'E, 2.24' - NOT ACCEPTED THIS SURVEY. CORNER FALLS ON A GENTLE NORTHWEST SLOPE IN TIMBER. FENCE RUNS NORTHWEST-SOUTHEAST. SCRIBED A 9" WHITE FIR, S2W, 14.4' "C 1/4 S8 BT" SCRIBED AN 11" WHITE FIR, N85E, 17.8' "C 1/4 S8 BT"	T23N R7E 1/4 S4 S3 LS 4753 2004 CORNER No. 13 SET A USFS DRIVE IN MONUMENT - NO MOUND. FROM WHICH A 1-1/2" ALUM. CAP ON A 1/2" REBAR MARKED RCE 13528 PER (1) BEARS N15°56'W, 98.9' - NOT ACCEPTED THIS SURVEY. CORNER FALLS ON A MODERATE SOUTHWEST SLOPE IN TIMBER, 150'± NORTHEAST OF A ROAD. SCRIBED A 7" INCENSE CEDAR, N26E, 13.2' "CN 1/16 S8 BT" SCRIBED A 15" WHITE FIR, S70E, 9.3' "CN 1/16 S8 BT"	T23N R7E 1/4 S3 S2 LS 4753 2004 CORNER No. 14 FD. A 3/4" ROD TAGGED LS 5309 IN THE ROOT BALL OF AN UPROOTED FIR. SET A USFS DRIVE IN MONUMENT IN A MOUND OF STONE FROM BEARING TREE. CORNER FALLS ON A MODERATE WEST SLOPE IN SCATTERED TIMBER AND BRUSH. SCRIBED A 25" INCENSE CEDAR, N27 1/2E, 63.6' "C 1/4 S3 BT" SCRIBED A 19" INCENSE CEDAR, N18 1/4W, 71.5' "C 1/4 S3 BT"	T23N R7E 1/4 S4 S3 LS 4753 2004 CORNER No. 15 FD. A 1/2" IRON PIPE WITH NO ID IN A MOUND OF STONE. SET A USFS DRIVE IN MONUMENT IN PLACE OF PIPE, REBUILT MOUND AND LAID PIPE ALONGSIDE. CORNER FALLS ON A GENTLE NORTH SLOPE IN TAMARACK, 120'± SOUTH OF THE EDGE OF BUCKS LAKE. FD. A ROTTEN TAMARACK STUMP, N15W, 11.2' -NO MKS REC. A 10" TAMARACK, N15W, 17 LKS (GLO) FD. TAMARACK REMAINS S47E, 30'± - PARTIAL FACE WITH HACK MARK REC. A 15" TAMARACK, S47E, 45 LKS (GLO) SCRIBED A 13" TAMARACK, S32 1/2E, 19.2' "1/4 S10 BT" SCRIBED A 12" TAMARACK, N57 1/2E, 20.5' "1/4 S3 BT"	T23N R7E 1/4 S2 S1 LS 5623 1995 CORNER No. 16 FD. A 1/2" IRON PIPE WITH NO ID IN A MOUND OF STONE. CORNER FALLS IN A MEADOW WITH SCATTERED TAMARACK. FD. A 23" TAMARACK STUMP, S30 1/2W, 28.4' -VS REC. A 27" PINE, S28W, 28.5' (12 R/S 126) FD. A 31" TAMARACK, N29 1/2E, 86.5' -HB REC. A 27" PINE, N32E, 86.4' (12 R/S 126)
T24N R7E R6E S36 TR42P4 S1 R6E T23N 1938 CORNER No. 4 FD. A GLO BRASS CAPPED IRON PIPE, NO MOUND. CORNER FALLS ON A STEEP SOUTHERLY SLOPE IN OLD TIMBER. FD. A 24" SUGAR PINE, N62W, 29.7' -NO MKS VISIBLE REC. 5" SUGAR PINE, N62 1/4W, 45 LKS (GLO) FD. A 34" WHITE FIR, N47W, 67.3' -HB REC. A 16" WHITE FIR, N47W, 102 LKS (GLO)	T23N R7E 1/4 S7 S8 LS 4753 2004 CORNER No. 11 FD. A 3/4" IRON PIPE - OUT OF GROUND. SET A USFS DRIVE IN MONUMENT FROM BEARING TREES. CORNER FALLS ON A GENTLE NORTH SLOPE IN TAMARACK AND FIR ON THE SOUTH EDGE OF GRUBBS LOG ROAD. FD. A 24" SUGAR PINE, N62W, 29.7' -NO MKS VISIBLE REC. 5" SUGAR PINE, N62 1/4W, 45 LKS (GLO) FD. A 34" WHITE FIR, N47W, 67.3' -HB REC. A 16" WHITE FIR, N47W, 102 LKS (GLO)	T23N R7E 1/4 S7 S8 LS 4753 2004 CORNER No. 12 SET A USFS DRIVE IN MONUMENT IN A MOUND OF STONE. FROM WHICH A 1-1/2" ALUM. CAP ON A 1/2" REBAR MARKED RCE 13528 PER (1) BEARS N88°12'E, 2.24' - NOT ACCEPTED THIS SURVEY. CORNER FALLS ON A GENTLE NORTHWEST SLOPE IN TIMBER. FENCE RUNS NORTHWEST-SOUTHEAST. SCRIBED A 9" WHITE FIR, S2W, 14.4' "C 1/4 S8 BT" SCRIBED AN 11" WHITE FIR, N85E, 17.8' "C 1/4 S8 BT"	T23N R7E 1/4 S4 S3 LS 4753 2004 CORNER No. 13 SET A USFS DRIVE IN MONUMENT - NO MOUND. FROM WHICH A 1-1/2" ALUM. CAP ON A 1/2" REBAR MARKED RCE 13528 PER (1) BEARS N15°56'W, 98.9' - NOT ACCEPTED THIS SURVEY. CORNER FALLS ON A MODERATE SOUTHWEST SLOPE IN TIMBER, 150'± NORTHEAST OF A ROAD. SCRIBED A 7" INCENSE CEDAR, N26E, 13.2' "CN 1/16 S8 BT" SCRIBED A 15" WHITE FIR, S70E, 9.3' "CN 1/16 S8 BT"	T23N R7E 1/4 S3 S2 LS 4753 2004 CORNER No. 14 FD. A 3/4" ROD TAGGED LS 5309 IN THE ROOT BALL OF AN UPROOTED FIR. SET A USFS DRIVE IN MONUMENT IN A MOUND OF STONE FROM BEARING TREE. CORNER FALLS ON A MODERATE WEST SLOPE IN SCATTERED TIMBER AND BRUSH. SCRIBED A 25" INCENSE CEDAR, N27 1/2E, 63.6' "C 1/4 S3 BT" SCRIBED A 19" INCENSE CEDAR, N18 1/4W, 71.5' "C 1/4 S3 BT"	T23N R7E 1/4 S4 S3 LS 4753 2004 CORNER No. 15 FD. A 1/2" IRON PIPE WITH NO ID IN A MOUND OF STONE. SET A USFS DRIVE IN MONUMENT IN PLACE OF PIPE, REBUILT MOUND AND LAID PIPE ALONGSIDE. CORNER FALLS ON A GENTLE NORTH SLOPE IN TAMARACK, 120'± SOUTH OF THE EDGE OF BUCKS LAKE. FD. A ROTTEN TAMARACK STUMP, N15W, 11.2' -NO MKS REC. A 10" TAMARACK, N15W, 17 LKS (GLO) FD. TAMARACK REMAINS S47E, 30'± - PARTIAL FACE WITH HACK MARK REC. A 15" TAMARACK, S47E, 45 LKS (GLO) SCRIBED A 13" TAMARACK, S32 1/2E, 19.2' "1/4 S10 BT" SCRIBED A 12" TAMARACK, N57 1/2E, 20.5' "1/4 S3 BT"	T23N R7E 1/4 S2 S1 LS 5623 1995 CORNER No. 16 FD. A 1/2" IRON PIPE WITH NO ID IN A MOUND OF STONE. CORNER FALLS IN A MEADOW WITH SCATTERED TAMARACK. FD. A 23" TAMARACK STUMP, S30 1/2W, 28.4' -VS REC. A 27" PINE, S28W, 28.5' (12 R/S 126) FD. A 31" TAMARACK, N29 1/2E, 86.5' -HB REC. A 27" PINE, N32E, 86.4' (12 R/S 126)	
T23N R7E 1/4 S12 S7 LS 4753 2004 CORNER No. 5 SET A USFS DRIVE IN MONUMENT AT PROPORTIONED POSITION. CORNER FALLS ON A STEEP EAST SLOPE. SCRIBED AN 11" WHITE FIR, S48E, 30.6' "T23N R7E S7 BT" SCRIBED AN 11" WHITE FIR, S45W, 23.0' "T23N R6E S12 BT" SCRIBED A 15" RED FIR, N68E, 44.1' "T23N R7E S6 BT"	T23N R7E 1/4 S12 S7 LS 4753 2004 CORNER No. 6 FD. A 1-1/2" IRON PIPE IN A MOUND OF STONE. CORNER FALLS ON A STEEP SOUTHEAST SLOPE IN LARGE TIMBER. FD. A 37" PONDEROSA, N80W, 33.0' -HB REC. A 31" PINE, N80W, 53 LKS (1) FD. A 13" WHITE FIR, N34E, 6.6' -OPEN SCAR, NO VS REC. A 10" FIR, N34E, 6.6' (1)	T23N R7E 1/4 S12 S7 LS 4753 2004 CORNER No. 7 FD. A 1/2" IRON PIPE TAGGED RCE 13528 IN A MOUND OF STONE. CORNER FALLS ON A STEEP EAST SLOPE, 150'± WEST OF A SHARP RAVINE. FD. A 14" WHITE FIR, N43W, 14.5' -HB REC. A 12" FIR, N43W, 22 LKS (1) FD. A 15" WHITE FIR, N34 1/2E, 7.3' -HB REC. A 13" FIR, N34 1/4E, 11 LKS (1) FD. A 12" FIR SNAG, S55W, 29.0' -VS REC. A 10" FIR, S55W, 44 LKS (1) FD. A 45" WHITE FIR, S15E, 91.7' -HB REC. A 40" FIR, S15E, 139 LKS (1)	T23N R7E 1/4 S12 S7 LS 4753 2004 CORNER No. 8 FD. A 1/2" IRON PIPE TAGGED RCE 13528 IN A MOUND OF STONE. CORNER FALLS ON A STEEP EAST SLOPE, 150'± WEST OF A SHARP RAVINE. FD. A 14" WHITE FIR, N43W, 14.5' -HB REC. A 12" FIR, N43W, 22 LKS (1) FD. A 15" WHITE FIR, N34 1/2E, 7.3' -HB REC. A 13" FIR, N34 1/4E, 11 LKS (1) FD. A 12" FIR SNAG, S55W, 29.0' -VS REC. A 10" FIR, S55W, 44 LKS (1) FD. A 45" WHITE FIR, S15E, 91.7' -HB REC. A 40" FIR, S15E, 139 LKS (1)	T23N R7E 1/4 S12 S7 LS 4753 2004 CORNER No. 9 SET A USFS DRIVE IN MONUMENT, NO MOUND. FROM WHICH A 1-1/2" ALUM. CAP MARKED RCE 13528 ON A 1/2" REBAR PER (1) BEARS S1			