


Lots 285, 293, 294, 295, 297, 298, 299, 300, 302, 303, 308, 309,  
and 310, Unit 12 "NAKOMI", 8 M 112  
and  
Lots 397 thru 402, Unit 16 "EAGLE FEATHER", 8 M 141

LINE	BEARING	LENGTH
L1	N39°50'48"E	45.77'
L2	N64°21'46"E	48.99'
L3	N88°07'05"E	41.55'(R1)
L4	N39°50'48"E	35.56'
L5	N36°56'51"W	34.05'
L6	N36°56'51"W	35.28'(R1)
L7	S70°57'52"E	9.47'
L8	S70°57'52"E	10.73'
L9	S27°15'15"W	30.31'
L10	S70°57'52"E	20.03'



The Basis of Bearings of this map is the Northwesterly line of Lot 310 Westerly of Lots 306 thru 308 shown as S40°02'44"W, in Book 8 of Maps at page 112, Plumas County records.

Note: all bearings, distances and curve data shown are record per Gold Mountain Unit 12 "NAKOMI", 8 M 112, and Gold Mountain Unit 16 "EAGLE FEATHER", 8 M 141, except those shown with (R1 & R2) which are measured and record per Lot Line Adjustment Document 2000-4927 and Document 2000-07966.



LEGEND

- FOUND point as described
- FOUND Rebar with Aluminum Cap LS 2843
- SET 5/8" Rebar with Aluminum Cap LS 2843
- Nothing found or set
- (R1) Record per Document 2000-4927
- (R2) Record per Document 2000-07966

RECORD OF SURVEY  
for  
Gold Mountain Ranch, Inc.

A portion of Section 22  
T. 22 N., R. 13 E., M.D.M.  
Plumas County ~ California  
Scale 1" = 100' ~ November 2000

Hamby Surveying Inc.  
P.O. Box 1209  
Portola, CA 96122  
(530) 832-5571